

|  |  |   |
|--|--|---|
| <b>Site Name</b>   | <b>Township</b>  | <b>Latitude</b>                                       |
| BF29   | 31N  | 48° 28.0627'N   |
| <b>Site Address</b>  | <b>Range</b>   | <b>Longitude</b>                                      |
| RR 1 Box 66<br>Harlem, MT 59526                                  | 23E  | 108° 45.0371'W  |
| <b>Land Ownership Status</b>                                     | <b>Section</b>   | <b>Location Method</b>                                |
|  | 4  | GPS NAD83   |
| <b>Type of Site</b>  | <b>Part of Section</b>   | <b>Directions to Site</b>                             |
| Old burned abandoned house/scattered dump located in the coulee. |  | Site located behind Newtown housing in nearby coulee. |
| <b>Site Size in Acres</b>  | <b>Allotment Number</b>  |   |
| 30 to 50 acres.  |  |   |
| <b>Property History</b>  |  |   |
| Home site/community dump.  |  |   |
| <b>Current Use</b>   |  |   |
| Residential/old dump site.                                       |  |   |
| <b>Assessment Funded by:</b>                                     |  |   |
| <b>Assessment Completed by:</b>                                  |  |   |
| <b>Site Inventory Date</b>                                       | <b>Known / Potential Environmental Concerns</b>  |   |
| 09/07/2006   | Comments: Community dump with household waste, appliances, metal debris, plastics, mainly household waste, and household appliances, and there are possible old junk vehicles located further down the coulee from the site. Runoff from storm events drainage flows into coulee and into stream and there is a pond located further up from the coulee. |   |
| <b>Phase I Date</b>  | <b>Known Environmental Concerns/Recommendations</b>  |   |
| <b>Phase II Date</b>   | <b>Corrective Actions/Cost and Re-use Options</b>  |   |

